






**Tree Removals. 2018 (Summer)**

	<p>7223 Herrick Park, Back Yard Under HPP Wires</p>	<p>25+ Ash</p>	<p>Dead, Line Clearance</p>	<p>Remove</p>	<p>2018</p>
	<p>7754 Herrick Park, Opposite Side of Street Under HPP Wires</p>	<p>15" Mulberry</p>	<p>Traffic Vista, Line Clearance</p>	<p>Remove</p>	<p>2018</p>
	<p>67 East Case, Side Yard Only, Under HPP Single Phase</p>	<p>10", 12" Spruce</p>	<p>Line Clearance</p>	<p>Remove</p>	<p>2018</p>
	<p>94 Aurora, Back Yard Under HPP Wires</p>	<p>6", 12", 24" Ash, and 14" Elm</p>	<p>Line Clearance</p>	<p>Remove</p>	<p>2018</p>

**Tree Removals: 2018 (Summer)**

	1559, 1577 Groton, Front Yard Under HPP Wires	6", 12" Linden, 5" Maple	Line Clearance	Remove	2018
---	--	-----------------------------	----------------	--------	------