




Tree Removals: 2018 (14)

	<p>140 Elm, Back Yard Near HPP Wires</p>	<p>18" Ash</p>	<p>Dead, Line Clearance</p>	<p>Remove</p>	<p>2018</p>
	<p>141 Colony, Backyard Near HPP Wires</p>	<p>Tallhedge Clump, 6" Ash</p>	<p>Dead, Line Clearance</p>	<p>Remove</p>	<p>2018</p>
	<p>222 East Streetsboro, Backyard Near HPP Wires</p>	<p>30" Maple in Fence, Marked Brush</p>	<p>Line Clearance</p>	<p>Remove</p>	<p>2018</p>